


### POWER CONNECTIONS


| FOR 105 V.A.C.      | FOR 210 V.A.C.    |
|---------------------|-------------------|
| JUMPER 1 & 5        | JUMPER 2 & 5      |
| JUMPER 2 & 6        | LINE 1 & 6        |
| LINE 1 & 6          | MOTOR 5 & 6       |
| MOTOR 1 & 6         |                   |
| A.C. LINE FUSE 7.5A | A.C. LINE FUSE 4A |
| FOR 117 V.A.C.      | FOR 235 V.A.C.    |
| JUMPER 1 & 5        | JUMPER 2 & 3      |
| JUMPER 2 & 3        | JUMPER 4 & 5      |
| JUMPER 6 & 7        | JUMPER 6 & 7      |
| JUMPER 4 & 8        | LINE 1 & 8        |
| LINE 5 & 8          | MOTOR 5 & 8       |
| MOTOR 5 & 8         |                   |
| A.C. LINE FUSE 7.5A | A.C. LINE FUSE 4A |

### NOTES:

1. FOR 105 OR 117 V.A.C. USE 7.5A FUSE & 130V. VARISTOR #5A-9044
2. FOR 210 OR 235 V.A.C. USE 4A FUSE & 275 V. VARISTOR #5A-9063.



**CONTACT  
POWER WIRING  
SOLID STATE SOUND**



**CONTACT**  
CABINET WIRING DIAGRAM  
SOLID STATE SOUND

