


TRANSFORMER
WIRING FOR
220/240 V.
50/60 INPUT




FOR 240 V. OR 240 V. INPUT TIE
LUG 1 AND LUG 3 TOGETHER.
70-1 (ORANGE) WIRE ON LUG 1

(115 V. TAP)

FOR 240 V. SOLDER 30-2P
(YELLOW) WIRE ON LUG 7

FOR 220 V. SOLDER 30-2P
(YELLOW) WIRE ON LUG 9

TRANSFORMER
WIRING FOR
115 V.
50/60 INPUT



FOR 115 V. INPUT TIE
LUG 1 AND LUG 3
TOGETHER. ALSO TIE
LUG 5 AND LUG 7
TOGETHER. 70-1P
(ORANGE) WIRE ON LUG 1

NOT USED

FOR 115 V. 30-2P
(YELLOW) WIRE
ON LUG 5