

CHANGE NOTICE

RELAY COILS ON THE FOLLOWING HAVE BEEN CHANGED

FROM #G-30-1500 TO #G-34-580/2020 AND A BREAK SWITCH WAS
ADDED TO EACH TO ACCOMMODATE THE DOUBLE-WOUND COILS.

MUSHROOM-BUMPER RELAY

OPEN GATE TARGET RELAY

EXTRA BALL TARGET RELAY

RELAY COILS ON THE FOLLOWING HAVE BEEN CHANGED

FROM #G-30-1500 TO #G-31-2100

10 POINT RELAY

100 POINT RELAY

1000 POINT RELAY

BALLY MFG. CORP.

Jan. 6, 1971

NEW COIL NUMBERS

FO-319a

OLD COIL NUMBERNEW BALLY COIL NUMBER

CO-25A-7	A-25-1050
CO-25GG-7	B-25-925
CO-25H-7	BC-25-925
CO-26A-9	A-26-1100
CO-26GG-9	B-26-1100
CO-27R-11	C-27-1000
CO-28R-15	C-28-1100
E-184-41	BF-27-1250
E-184-46	EA-30-1150
E-184-47	EA-32-1550
E-184-55	B-29-1200
E-184-56	A-27-1100
E-184-74	CF-28-1025
E-184-75	E-32-1700
E-184-112	EA-29-950
E-184-135	BA-25-925
E-184-155	D-27-425
E-184-156	D-28-500
E-184-160	B-25-750
E-184-175	AP-27-1300
E-184-180	CE-33-4800
E-184-190	AF-25-600/31-1000
E-184-204	AF-27-1000/32-1300
E-184-205	B-27-1300
E-184-206	CD-29-1600
E-184-207	A-27-1400
E-184-213	A-27-1300
E-184-218	F-31-1500
E-184-224	F-31-2100
E-184-231	CA-29-800/31-900
E-184-235	AK-25-1050
E-184-236	J-28-1100
E-184-237	BA-26-1040
E-184-241	AF-25-600/31-1000
E-184-243	A-26-1200
E-184-248	FC-30-1300
E-184-249	BF-28-1500
E-184-250	D-30-700
E-184-252	BB-26-655/32-1245
E-184-254	FC-30-1400
E-184-257	AP-25-1050
E-184-260	B-28-1600
E-184-261	AP-31-3000
E-184-262	A-26-1200
E-184-263	AF-27-775/31-861
E-184-264	A-28-1900
E-184-265	AF-25-600/31-1000
E-184-266	D-29-675
E-184-268	AF-26-750/31-900
E-184-269	FC-33-2600
E-184-270	AB-31-3000
E-184-271	AK-24-750
E-184-272	A-25-1000
E-184-274	FC-32-2100

NOTE:

THESE COILS MAY BE ORDERED BY THE OLD COIL NUMBER OR BY THE NEW COIL NUMBER OR BY BOTH.