



BOOMERANG

WIRING DIAGRAM CORRECTION



CORRECTION:
THE EXTRA BALL RE.
SHOULD READ AS
SHOWN.

LOCATION F - 9



CORRECTION:
THE PLAYER UP UNIT
DISC IS NOT IDENTI-
FIED AS SUCH.

LOCATION D - 18