

AJUSTE DE LOS CONTACTOS

ANTES DE AJUSTAR, ASEGURESE DE QUE LOS TORNILLOS QUE SUJETAN EL PAQUETE DE CONTACTOS ESTAN APRETADOS.







LOS SEPARADORES DE BAQUELITA, DEBIDO A LA EXCESIVA HUMEDAD, OCASIONALMENTE SE CONTRAEN AL SECARSE, CAUSANDO MALOS AJUSTES.

SWITCH ADJUSTMENT


BEFORE ADJUSTING SWITCHES, MAKE CERTAIN THE SCREWS HOLDING THE SWITCH STACKS ARE DOWN TIGHTLY. BAKELITE SPACERS IN THE SWITCH STACKS, DUE TO EXCESSIVE MOISTURE, HAVE OCCASIONALLY SHRUNK BY DRYING OUT, CAUSING POOR ADJUSTMENT.

"CANNES"







FUENTE DE ALIMENTACION
MECHANISM PANEL




CONTADOR MONEDAS
COIN UNIT



CONTADOR BOLAS
BALL COUNT UNIT



AJUSTE 25 PTS.
25 ¢ ADJ. JACK



1 MONEDA 1 PARTIDA
COIN PLAY
2 MONEDAS 3 PARTIDAS
COINS PLAY

AJUSTE 10 PTS.
10 ¢ ADJ. JACK

